

RIVO MULTITRADE OPTICAL SYSTEMS

How to connect a thick fiber optic fusion splice patch cord



Overview

Learn fiber splicing and winding in 5 steps with pro tips on stripping, cleaving, fusion, and sleeve protection.

Key Takeaways

To connect a thick fiber optic fusion splice patch cord, carefully strip, clean, cleave, fuse, and protect the fiber to ensure minimal signal loss and long-term reliability.

Tools and Materials Needed

- Fiber optic stripper and cable stripper
- Kevlar cutter
- High-precision fiber cleaver
- Fusion splicer
- Fiber cleaning supplies (lint-free wipes, isopropyl alcohol)
- Heat shrink protective sleeves and oven
- Fiber splicing tray or patch panel
- Visual fault locator (VFL) or OTDR for testing

- Safety glasses for eye protection

Step 1: Cable Preparation

- Remove the outer jacket of the fiber optic cable using a cable stripper, exposing the inner fibers.
- Cut and remove strength members (e.g., Kevlar) with a Kevlar cutter.
- Strip the fiber coating carefully to expose the bare fiber, keeping the fiber steady and horizontal to avoid slipping .
- Clean the bare fiber with alcohol-soaked lint-free wipes to remove any residue or adhesive layers .

Step 2: Cleaving the Fiber

- Use a high-precision cleaver to create a smooth, perpendicular end-face on the fiber.
- Avoid angled cuts, cracks, or burrs, as these can increase signal loss .
- Handle the cleaved fiber carefully to prevent contamination or damage.

Step 3: Fusion Splicing

- Insert a protective sleeve onto the fiber before splicing; this will cover the splice after fusion .
- Place the prepared fiber ends into the fusion splicer, aligning them precisely.
- Activate the splicer to fuse the fibers using an electric arc, creating a permanent, low-loss joint .
- Inspect the splice using the splicer's microscope or a VFL to ensure proper alignment and minimal back reflection.

Step 4: Protecting the Splice

- Slide the heat shrink sleeve over the fused joint.
- Use a heat oven or splicer's built-in heater to shrink the sleeve, providing mechanical protection and strain relief .
- Place the protected splice into a splice tray or patch panel, coiling the fiber carefully to avoid sharp bends. Maintain a bending radius at least ten times the fiber diameter, typically no less than 30 mm .

Step 5: Testing

- Use a VFL or OTDR to verify the splice quality and ensure minimal signal loss.
- Document the splice location and test results for future maintenance.

Tips for Thick Fiber Cables

- For multi-fiber or thick patch cords, handle fibers individually and route them carefully to prevent tangling.
- Work in a clean, dust-free environment to avoid contamination.

- Avoid exposing bare fibers to air for extended periods to prevent dust or moisture contamination . By following these steps, you can achieve a reliable, low-loss fusion splice on thick fiber optic patch cords suitable for high-performance network applications .

Article Content

How to Splice Fiber Optic Cable – Step-by-Step Fusion Splicing Guide

Learn how to splice fiber optic cable using fusion splicing with this complete step-by-step guide. Includes tools, best

A comprehensive tutorial on how to connect fiber optic ...

By understanding the components, steps involved, and best practices, you can effectively use a fusion splicer to

How to Install Fiber Optic Pigtails (Step-by-Step Guide)

Align and fuse the pigtail fiber with the main cable. Apply a heat-shrink sleeve for durability. Use an OTDR or power

Fiber Splicing & Winding Tutorial – Step-by-Step Guide

Learn fiber splicing and winding in 5 steps with pro tips on stripping, cleaving, fusion, and sleeve protection. Ensure

How Do You Splice Fiber with a Fusion Splicer?

Mastering the art of fusion splicing fiber optic cables is a valuable skill that can enhance your connectivity

The Ultimate Guide to Splicing of Fiber: Techniques and Tips

Looking to understand fiber splicing? It's the process of joining two fiber optic cables using techniques such as fusion

How to Splice Fiber Optic Cable

Fiber optic fusion splicing is a crucial technique for connecting and repairing fiber optic cables, ensuring reliable

Mechanical Splice-On Fiber Connectors vs Fusion Splicing Guide

Learn how mechanical splice-on fiber connectors compare to fusion splicing for FTTH, enterprise, and field fiber

Guide for splicing of fiber optic fibers | EFB-Elektronik

Guide for proper splicing of fiber optic fibers Splicing has become an integral part, especially in the field of electrical installations. Find

The Complete Step-by-Step Guide to Fiber Optic Splicing

As fiber optic connections become increasingly mainstream, the need to connect fiber optic cables to one another — or splicing — is

Fiber Optic Splicing: A Beginner's Guide - VCELINK

Fiber optic splicing joins two fiber optic cables end to end seamlessly to create a continuous path for light signal,

Fiber Optic Fusion Splicing 101 (Hard Drops)

Best practices for a strong, reliable splice Whether you're a beginner or looking to refine your skills, this tutorial is

Fiber Optic Cable Splicing: A Comprehensive Guide

To support integrators, here's an easy to follow guide for fiber optic cable splicing discussing mechanical splicing and

The FOA Reference For Fiber Optics

The core of an optical fiber is quite small; so small that airborne dust is often as large as the core of singlemode fiber and even large

Mechanical vs. Fusion Splicing: Which Is Right for You?

Comparing mechanical and fusion splicing for fiber optic cabling: costs, performance, and more. Discover the right

How to Joint Fiber Optic Cables | Step-by-Step Fusion Splicing

In this video, learn how to *joint two fiber optic cables* using a fusion splicing method. Whether you're a beginner or a

FASTSPlice™ Fusion Splice-On Fiber Connectors

Leviton offers a full range of fusion fiber splicing solutions, including fiber splice modules in our popular HDX and SDX fiber optic

How to Splice Fiber Without a Fusion Splicer | Step-by-Step Guide

Not every fiber job comes with a fusion splicer. Whether you're working a tight-deadline repair, a field termination

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

Contact Us

Continue your research online:

Website: <https://rivomultitrade.co.za>

Technical inquiry: <https://rivomultitrade.co.za/contact.html>

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

