

RIVO MULTITRADE OPTICAL SYSTEMS

How to quickly strip a 12-core optical cable



Overview

Sheath Removal and Stripping of 8 and 12-Fiber Ribbon Do not crush the cable or allow it to kink. Doing so may cause damage that can alter the transmission.

Key Takeaways

Using a hand-held thermal stripper like the HS-12 is currently the fastest and most reliable method for stripping 12-core optical cables. Recommended Method: Thermal Stripping

For 12-core optical cables, thermal strippers are highly efficient because they soften the polymer coating with heat, allowing the buffer and jacket to be removed cleanly without nicking the fibers. The HS-12 thermal stripper is specifically designed for ribbon and multi-fiber cables up to 12 fibers, offering a heating time of just 4 seconds and approximately 500 cycles per full battery charge. This method minimizes manual effort and reduces the risk of microfractures compared to mechanical stripping.

Steps for Thermal Stripping:

- Prepare the cable: Cut the cable to the desired length and remove any outer tape wraps.
- Secure the fibers: Use removable fiber holders to keep the fibers aligned and prevent bending.
- Heat the coating: Activate the thermal stripper to soften the jacket and buffer.

- Remove the coating: Gently pull off the softened jacket and buffer, exposing the bare fibers for connectorization or splicing.

- Inspect fibers: Ensure no scratches or nicks are present on the glass cores.

Alternative Method: Mechanical Stripping

If a thermal stripper is unavailable, precision mechanical fiber strippers can be used. These tools have matched blades and fiber guides to strip the buffer without damaging the fiber. For multi-layer cables, stripping must be done progressively: first the outer jacket, then the aramid yarn, and finally the individual fiber buffers. Proper blade selection and maintenance are critical to avoid cutting the aramid yarn, which can compromise tensile strength.

Tips for Mechanical Stripping:

- Use a fiber gripper to hold the fiber securely without wrapping or clamping.
- Strip each layer to the required length individually.
- Keep blades sharp and clean to ensure smooth, clean cuts.

Summary

For speed and reliability, a thermal stripper like the HS-12 is the fastest method for 12-core optical cables, providing near-zero failure and minimal fiber damage. Mechanical strippers are a viable alternative but require careful progressive stripping and proper tool selection. Always inspect fibers after stripping to ensure they are ready for splicing or connectorization.

Article Content

Sheath Removal and Stripping of 8 and 12-Fiber Ribbon

Do not crush the cable or allow it to kink. Doing so may cause damage that can alter the transmission characteristics of the cable -

How long should a 12-core optical cable be stripped

Stripping a 12-core optical cable typically takes 10–20 minutes per cable, depending on skill level, tools, and cable type. Factors

Fiber and Cable Stripper – Types, Uses & Guide

Learn how to use fiber strippers, cable cutting scissors, and armored cable slitters. Discover their applications in fiber

Fiber U Lesson Plan: Basic Skills Lab, Remote

Use the fiber stripper to cut off 2" (50mm) of the cable jacket and pull off the cut piece. Use the first groove in the fiber stripper - the

How To Strip Fiber Optic Cable | Instructional

In this instructional video, Bob Licari, Test Equipment Product Manager, demonstrates a simple way to strip optical fiber.

Ultimate Guide: Fibre Optic Cable Stripping and Preparation

In this informative guide, we'll walk you through the step-by-step process of stripping and preparing fibre optic cable

How To Quickly and Easily Clean Up The Optical Cable?

Cleaning up an optical cable quickly and easily involves a few simple steps to ensure that it remains undamaged and

Fiber U Lesson Plan: Basic Fiber Optic Skills Lab

In this lesson, we will identify and examine cables, then prepare them for splicing or termination by stripping

Sheath Removal and Stripping of 8 and 12-Fiber Ribbon

1.2 Corning Cable Systems ribbon interconnect cables are lightweight, flame retardant cables designed for high performance

Stripping Techniques For Your Fiber Optic Cable Assembly Process ...

Good fiber optic stripping techniques in your cable assembly process are crucial. See best practices for how to strip

How to Terminate Fiber Optic Cable Fast and Easily

Fiber optic termination is a necessary step for installing a fiber optic network. It is a physical connection of a fiber optic

How to Repair Cut Fiber Optic Cables

Repair cut fiber cables with this step-by-step guide. Learn proper tools, techniques, and tips for effective fixes.

How To Strip Electrical Wire (With & Without Tools)

How to EASILY and QUICKLY strip cable & electrical wire. We go over how to strip wire with and without a tool, and

How to Strip Multi-Conductor Cables | Cable Stripping Guide

Whether you're making upgrades to an existing wiring configuration or starting a new project from scratch, you'll need

Fiber-optic cable

A fiber-optic cable, also known as an optical-fiber cable, is an assembly similar to an electrical cable but containing one or more

Fiber and Cable Stripper – Types, Uses & Guide

First, strip the outer sheath of the optical fiber with optical fiber strippers; remove the stripped outer sheath of the

Fiber Optic Termination Kit • User Guide

Core Glas Fiber Bufer Jacket and 3mm Kevlar Stans Fiber Strip 70 m Strip Cable 40 m 68-2049-01 A Cleave/Strip Gauge Cable

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

Contact Us

Continue your research online:

Website: <https://rivomultitrade.co.za>

Technical inquiry: <https://rivomultitrade.co.za/contact.html>

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

