


How to strip the inner core of an optical cable



Overview

Stripping Techniques For Your Fiber Optic Cable Good fiber optic stripping techniques in your cable assembly process are crucial. See best Ultimate Guide.

Key Takeaways

Stripping the inner core of an optical fiber involves carefully removing the protective coatings and buffers to expose the bare glass fiber without causing scratches or microfractures.

Understanding Fiber Layers

Optical fibers are typically composed of multiple layers: the outer jacket, aramid yarn or strength members, buffer coating, and the glass core/cladding. Each layer must be stripped progressively, starting from the outer jacket and moving inward, to avoid damaging the delicate inner core (). The core itself is usually 125 μm in diameter, with coatings increasing the total diameter to around 250 μm for standard telecom fibers ().

Tools for Stripping

Specialized fiber strippers are used to remove coatings cleanly. These tools can be mechanical, thermal, or non-contact, and are designed to match the fiber's coating diameter (). Key features include:

- Precision blades to avoid nicking the glass core.

- Fiber guides to ensure proper alignment.
- Color-coded blades for different fiber diameters.
- Grippers to hold the fiber securely without wrapping or clamping, which can create microfractures ().

For tight-buffered fibers, tools like the No-Nik® or Micro-Strip® kits can strip buffers up to 2360 µm and jackets up to 3.5 mm ().

Step-by-Step Stripping Process

- Measure and mark the length of coating to be removed according to connector or splicer specifications ().
- Strip the outer jacket carefully using the appropriate gauge stripper, avoiding damage to underlying aramid yarn or buffer ().
- Remove the buffer coating with a precision fiber stripper, exposing the bare glass core ().
- Clean the bare fiber using lint-free wipes and high-purity alcohol to remove any residue ().
- Inspect the fiber under a microscope for scratches or nicks before cleaving or connectorization ().

Safety Precautions

- Always wear safety glasses to protect against sharp glass fragments ().
- Handle fibers carefully to avoid microfractures, which can weaken the fiber and cause future failures ().
- Maintain stripper blades regularly to ensure clean cuts and prevent accidental damage ().

Additional Tips

- Avoid stripping more than 50 mm at a time to reduce the risk of fiber damage ().
- For specialty fibers with thinner coatings, adjust stripper settings or use tools designed for smaller diameters ().
- Use fiber grippers rather than clamping the fiber directly to prevent stress points ().

By following these techniques and using the correct tools, the inner core of an optical fiber can be safely exposed for splicing, connectorization, or other optical processing tasks.

Article Content

Ultimate Guide: Fibre Optic Cable Stripping and Preparation

In this informative guide, we'll walk you through the step-by-step process of stripping and preparing fibre optic cable

How to Properly Strip, Cut, and Test Fiber Optic Cables?

Use an optical fiber stripper to remove the protective outer sheath of the fiber cable. Hold the cable securely and apply consistent

Cable Preparation Best Practices for Fiber Optic Indoor/Outdoor ...

This best practices document is a step-by-step guide for end and midspan access of loose tube optical cable, including sheath

Essential Tools for Stripping Fiber Cable: A Comprehensive Guide

Discover the importance of proper fiber cable stripping techniques and tools, including the Fusion Splicer. Learn how

Tips & Techniques for Using Stripping Tools on Fiber Optic Cable

If the blade of the strip tool contacts the bare fiber, it's easy to scratch the fiber OD, reducing product reliability. Click

Fiber U Lesson Plan: Basic Fiber Optic Skills Lab

In this lesson, we will identify and examine cables, then prepare them for splicing or termination by stripping

Cable Preparation Best Practices for Fiber Optic Indoor/Outdoor ...

The cable core for high fiber count cables (greater than 144 fibers) may contain two layers of buffer tubes. Remove any additional

VHO-cables.ppt

After splitting the armor and outer jacket, the inner cable can be removed. Pull it out of the armor making certain that it is not bent too

Good stripping techniques for your fiber optic cable ...

Without question, good stripping techniques in your fiber optic cable assembly process are imperative. What happens if you damage

Basic Components of a Fiber Optic Cable – trueCABLE

A fiber optic cable consists of five basic components: the core, the cladding, the coating, the strengthening fibers, and

Fiber U Basic Skills Lab Workbook-termination

Fiber Optic Connector Termination Overview It was not long ago that the proper methods used to terminate fiber optic connectors

How To Terminate Fiber Optic Cable□

1. Prepare the Fiber Cable Strip the Cable Jacket: Use a fiber optic cable stripper to carefully strip back the outer

Fiber and Cable Stripper – Types, Uses & Guide

First, strip the outer sheath of the optical fiber with optical fiber strippers; remove the stripped outer sheath of the

An Overview Of Optical Fiber Cable Structure And Components

An optical fiber cable is a complex structure designed to protect fragile glass fibers that transmit digital data using light signals. This

How to Terminate Fiber in Seconds

In this video, we'll guide you through preparing and terminating fiber optic cables using SimplyFiber products, known

Fiber U Lesson Plan: Basic Skills Lab, Remote

Lesson: Stripping Optical Fiber Cable Objectives: From this lesson you should learn: How to use these tools to strip cable to the bare

How to Fix a Cut Fiber Optic Cable

While a cut or damaged fiber optic cable can temporarily take your network down, it is possible to quickly fix the cable

How to Repair a Fiber Optic Cable

Understanding how to repair your damaged fiber optic cable will help you keep your network online when the unexpected strikes.

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

Contact Us

Continue your research online:

Website: <https://rivomultitrade.co.za>

Technical inquiry: <https://rivomultitrade.co.za/contact.html>

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

